

Limetree CWA Incidents

#	DATE	DESCRIPTION	INCIDENT TYPE	AREA AFFECTED	PRODUCT	QUANTITY TO HARBOR	CORRECTIVE ACTION	Comments
1	08/06/16	An oil sheen was coming from tankfield drain west of 7423. Sheen got in the east basin north west corner.	Spill to Harbor	East Basin Outfall 008	Slop/Groundwater	Sheen	Notified Agencies, clean up, sump repairs (USCG \$500) 2019- new alarm system in place	Cover letter included
2	04/27/17	While draining the Chiksans at Dock No. 3 a leak developed on the drain line under the dock leading to the dock sump.	Spill to Harbor	East Basin Dock 3	Crude	20 gallons	Notified Agencies, used sorbents and cleaned (USCG \$1000)	Cover letter included,
3	07/15/17	Spill from OOS Piping at dock leaked into the harbor waters.	Spill to Harbor	West Basin, Dock 8	6 oil	<5 gallons	Deployed boom and boats with sorbents and vacuum truck. Reported to appropriate agencies. (USCG \$5,500)	Cover letter included
4	01/04/18	Failure in the weld of the low and high points on the 24" Bypass of the 42"C/L northeast of DK#7 caused Ekofisk crude to spill to ground and water.	Spill to Harbor	West Basin Dk 7	Crude	Sheen or <20 gallons	Notified Agencies, Bermed, boomed and cleaned (USCG \$8,000)	Cover letter included
5	11/04/18	An oil sheen was observed on the sea waters around the vessel Torm Sofia.	Spill to Harbor	East Basin	Hydraulic Oil	Sheen	Notified Agencies. Vacuumed apron and adjusted crane hoses, crane mechanically repaired	Cover letter included
6	09/06/19	End cap of Chicksans at Dock No. 4 leaked and caused a sheen.	Spill to Harbor	West Basin Dock 4	6 oil	Sheen	Notified Agencies, Tightened Flange and wrapped with sorbents	Cover letter included
7	11/09/19	Fire water line rupture causing discoloration to the harbor	Spill to Harbor	East Basin Dock 1	Silt	N/A	Notified Agencies, Secured system and repaired line	Cover letter included
8	01/11/20	While removing the outer arm of the Chicksan the counter weight fell and ruptured the 42" Crude header	Spill to Harbor	East Basin Dk 3	Crude	~20 gal	Notified Agencies, Boomed, cleaning, secured equipment	Cover letter included
9	03/21/20	Stormwater samples from Outfall 006 and 007 exceed Oil and Grease Limits	Permit Exceedance	Outfall 6 & 7	Unknown	Unknown (33.0 mg/l & 38.0 mg/L, respectively)	Walked area and found no evidence of source	Cover letter included
10	08/22/20	#3 API overflowed to the lagoon during TS Laura and slight sheen made it to the harbor	Spill to Harbor	West Basin Outfall 001	Slop	Sheen	Notified Agencies, Opened line to 7514, clean up of lagoon and Main Outfall, established new guidance, coached employees	Cover letter included
11	09/03/20	Oil from 3 Vac to the All American Canal and to the harbor	Spill to Harbor	West Basin Outfall 001	Diesel	Sheen	Notified Agencies, Boomed, vacuum trucks, cleaned stormwater system associated to event	Cover letter included
12	11/10/20	Oil backed up from oily water sewers at 3 Vac, coming from 6DD during heavy rains. Overflowed to storm drains and flowed sheen to the harbor.	Spill to Harbor	West Basin Outfall 001	Slop	Sheen	Notified Agencies, Boomed water way, discharged vac trucks, evaluating sewer system	Cover letter included
13	11/28/2020	Sulfide Exceedance on Outfall 401	Permit Exceedance	Outfall 401	Sulfide	32.83 lb/d not an exceedance	Investigation ongoing to determine if interference in lab results:	Note put in monthly DMR. DMR notes measurement below regulatory limit. ECHO notes percentage above regulatory limit (171.01 lb/d)
14	12/28/2020	Sulfide Exceedance on Outfall 401	Permit Exceedance	Outfall 401	Sulfide	146.12 lb/d		Note put in monthly DMR. DMR notes measurement below regulatory limit. ECHO notes percentage above regulatory limit (146.06 lb/d)
15	1/28/2021	Sulfide Exceedance on Outfall 401	Permit Exceedance	Outfall 401	Sulfide	196.59 lb/d		Note put in monthly DMR. DMR notes measurement below regulatory limit. ECHO notes percentage above regulatory limit (196.44 lb/d)
16	2/28/2021	Sulfide Exceedance on Outfall 401	Permit Exceedance	Outfall 401	Sulfide	218.03 lb/d		Note put in monthly DMR. DMR notes measurement below regulatory limit. ECHO notes percentage above regulatory limit (218.16 lb/d)